

To all Exhibitors;

We are pleased to announce that GES in partnership with TRADE-MARK INDUSTRIAL INC. will be the exclusive supplier of Rigging and Machinery Installation Services to the Canadian Manufacturing Technology Show 2021. As the specialized material handlers for CMTS 2021 in Toronto Ontario, we have prepared the following package of information and order forms for our services. Please review and complete the enclosed information accurately as we want to ensure that your move in and out runs as smoothly and efficiently as possible.

All work done at the show is based on the hourly rates (see Heavy Machinery Handling Order Form included in kit) and all payments are due in advance of the show.

In order to avoid delays in processing of both incoming and outgoing equipment, it is imperative that your method of payment be in our files prior to the start of the show.

We look forward to working with you, and wish you all great success at the Canadian Manufacturing Technology Show 2021.

Yours truly,

GES Trade-Mark Industrial Inc.

5675 McLaughlin Road, Mississauga, Ontario, L5R 3K5 Tel: 905-283-0500 Toll Free: 1-877-437-4247 www.ges.com/ca

HEAVY MACHINERY HANDLING SUGGESTIONS FOR A SMOOTH/COST EFFECTIVE SHOW

Please ensure that your staff and technicians responsible for loading or for preparing the booth at the show have been given a copy of this list. If you follow the basic rules provided, the experience should be a good one and your costs will be kept to a minimum.

1) Loading Please ensure your trucks are loaded friendly for removal.

IE: On at least 4 - 6" blocking, fork pockets turned to side of trailer bed.

*(Boom lifts take more time than forks)

2) Special Rigging Please ensure any special rigging that makes the installation of your equipment

easier has been shipped with your equipment and that the technicians are aware.

(ie: Spreaders)

3) Skidding & Boxes Skidding and Boxes require additional work to remove.

Either leave skidding on equipment or reduce their use.

BOXES & SKIDDING MUST BE KEPT OUT OF THE AISLES.

4) Labelling Be sure all additional components that you will want stored away from

your booth (ie: skids, containers, boxes etc.) are clearly labelled to avoid delays in finding them. Please label clearly with Large Print the

company name and booth number.

5) Final Placement Take the time to be sure of the exact final location of your machinery,

BEFORE WE ARRIVE. Relocating machinery is costly.

6) Authority Please instruct the person in charge during installation that they have

your authority and that they will be signing for the work performed in that booth. Maintain all copies of TIME SHEETS so that you have a

record for your company.

7) Planning Plan your work prior to our arrival to minimize the amount of wasted

time due to decision making. This will also minimize the number of

return visits.

8) Organize Organize your truckloads to match your booth expectations.

Good organization at home will be more cost effective than trying to

organize at the show.

9) Credit Cards Be sure you have completed the credit card section of our Heavy

Machinery Handling order form. This helps to eliminate any on-site

delays relating to payment.

10) Payments All payments will be required on Credit Card or Certified Cheque prior

to the reloading of any equipment.



2021 CMTS MOVE - IN HEAVY EQUIPMENT REGISTER



LIST ONLY INDIVIDUAL PIECES OF EQUIPMENT WEIGHING OVER 5,000 LBS.

Deadline to submit form: August 20, 2021

Machine Type	Weight	Height	B	Base	Crated	ed	Skidd	P P	Skidded Pre-Rigged	Special Instructions	Date/Time In	
			Length (ft)	idth (ft)	Yes	N _o	Yes	N _o			(for office use only)	only)
										,		
Company										Contact:		
Address										E-Mail:		
Postal/Zip Code:										Phone:		
Booth Number (s):										Fax :		
Booth Carpet Provided By (Please check one of the followi	l By (Please σ	check one o	f the followir	ing):		GES			ndependen	Independent company provided by exhibitor	by exhibitor	

PLEASE RETURN COMPLETED FORM TO:

torontoexhibitorservices@ges.com