

The International Centre Electrical and Mechanical Services

SHOWTECH POWER & LIGHTING is the exclusive provider of power, electrical distribution, lighting, electrical connections for machinery and equipment, air and water connections, sign and banner hanging from the building structure, as well as man lifts and operators.

- **SHOWTECH order forms can be downloaded at** <https://e.showtechordering.com/ST-00042576/downloadForms>
- **To order SHOWTECH services/products online for CMTS, go to** <https://e.showtechordering.com/ST-00042576>

ELECTRICAL

1. The International Centre voltages are 600/120/208 volts 3 phase. Please check with your technical coordinator to see if your machines are compatible with these voltages. If so, you will save on costs.
2. All other voltages are available from SHOWTECH with the use of a transformer. Transformers must be placed within your booth space so please allow for the transformer when you do your space plan/layout. Approximate size can be provided by SHOWTECH (see below for contact info).
3. Transformers will be required on 208 volt connections greater than 30 amps.
4. 600 volt connections do not require a transformer.
5. The International Centre does not have floor ports.
6. Power will be distributed by SHOWTECH from exterior walls, columns (in some buildings) and cable drops from the ceiling. To order power, please use the links above.
7. If you have an Island booth, please indicate a main power drop location on SHOWTECH's Booth Layout Form and submit the form with your Electrical Order Form. We will distribute under carpet outlets from that location.

Ontario's Electrical Safety Authority (ESA) requires that all machinery that will be displayed and/or powered up during CMTS must be approved by the ESA before show opening. Exhibitors are responsible to obtain "Permission to Show/Energize" from the ESA directly. SHOWTECH cannot apply or be responsible for this permission. To obtain the ESA "Permission to Show/Energize", go to <http://www.esasafe.com/contractors/worker-safety/product-review/product-approval-requirements> to apply for permission/approval from the ESA. **Apply as soon as possible to avoid onsite complications.**

MECHANICAL

8. Compressed air pressure is approximately 110 PSI and available anywhere in the facility by ordering from SHOWTECH. Please use the SHOWTECH Mechanical Order Form found on the links listed above.
9. The International Centre does not have floor ports.
10. Air lines are distributed by SHOWTECH from exterior walls, dropped from the ceiling or from columns (in some buildings).
11. Only ½" air lines can be run under carpet in booths.
12. If you are in an island booth, please indicate a main air drop location on SHOWTECH's Booth Layout Form and submit with your Mechanical Order Form. SHOWTECH will distribute any under carpet requirements from that location.
13. Water pressure is approximately 50 PSI and available anywhere in the facility by ordering from SHOWTECH's Mechanical Order Form.
14. If you require hot water for your booth, an electric hot water tank will need to be installed by SHOWTECH within your booth space. Please plan accordingly and notify us in the Specialty Items space on the bottom of the SHOWTECH Mechanical Order Form or call for assistance (905-677-9546).
15. Natural gas is available in various locations within the facility. Please check with SHOWTECH (905-677-9546) or Show Management, as soon as possible, if you require Natural Gas.
16. Sanitary floor drains are located in various locations within the facility. Please check with SHOWTECH (905-677-9546) or Show Management, as soon as possible, if you require a drain connection.

SHOWTECH POWER & LIGHTING contact information: Ilda Sullivan
Telephone: 905-677-9546
Email: isullivan@showtech.ca

